






## A8050 Chain-A-Part<sup>®</sup>

### Operating Instructions

#### DO NOT USE AN IMPACT WRENCH

- 

1. Place chain in position against indentation in bottom clamping jaw, and tighten knurled clamping cylinder. This aligns punch automatically with connecting pin.
- 

2. Screw down hex head on punch screw with wrench to force connecting pin completely out.
- 

3. Back off clamping cylinder to extract punch from chain, and your chain is completely apart!

Replacement Parts: A8053 Punch; A8054 Sleeve; A8008 Screw

P.O. Box 17364 Wichita, Kansas 67217-0364 Phone (316) 942-8632

[www.smithtoolinfo.com](http://www.smithtoolinfo.com)